



Product Maintenance Update:



In order to maintain the warranty on your recent purchase of Tuffmat™ Zero-fill® wear mats, proper installation and maintenance of Woodcarpet® engineered wood fiber must be maintained at proper levels around the mat.



As the picture indicates in the background; maintain the EWF to within a half inch of the top of the mat to maintain accessibility and prevent a trip hazard.

In the foreground the surface has never been maintained to the edge and has exposed the mat which causes a trip hazard and negates any access on and off the wear mat.

Zeager TuffMats™ will reduce maintenance and maintain a safe fall surface for your playground but proper maintenance is still needed to allow them to perform as designed and maintain the warranty. Go to our website and click on the Planning & Resources link to see a video on how to properly install TuffMat™ ZeroFill® mats—<https://www.zeager.com/planning-resources/installation> .

Zeager Bros. Inc. Main: 4000 E. Harrisburg Pike Middletown, PA 17057

PA office: 1-800-346-8524 / KY office: 1-800-296-9227

West US Territories: 1-800-346-8524 X 292

Canadian Territories: 1-800-346-8524 X 291

